CORNER RECORD	Document Number
	County of, California
Brief Legal Description <u>LOT 60 120 NDIERO</u> Book "H" OF M. 9.	OSA PALISADES UNIT #1
SEC. 15 CORNER TY	PE COORDINATES (Optional)
+ R.16E Meander	Control
Rancho □ Date of Survey 6/2	
orner – Left as found ☐ Found and tagged ☐	☐ Established ☐ Reestablished ☐ Rebuilt ☐
dentification and type of corner found: Evidence used to identi	ify or procedure used to establish or reestablish the corner:
= FOUND 5/8" REBAR W/PLAST	SECIENE TO BE ORIGINAL MR H/MAS/50 CLPWG, R.C. E 20257, 1.5' BELOW GROUND
	<u> </u>
A description of the physical condition of the monument as fou	nd and as set or reset:
0 = SET I" IRON PIPEW/PLAS	STIE PUG. 6.5.5549
	·
VN. 04105	STATE OF THE PARTY
•	SED LAND SCOR
SURVEYOR'S STATEMENT	SR C. TEN
his Corner Record was prepared by me or under my direct	tion in conformance with
ne Land Surveyor sact on	2004
/	4 7 4
Signed P.L.S or R.C.E. No.	Exp (/30/05
COUNTY SURVEYOR'S STATEMENT	AND COM A
his Corner Record was received OCTOBER 21	. 04
and examined and filed NOVEMBER 10, 2004	CHARLES B. GRANT
Signed Churle B. Sport P.L.S or R.C.E. No	
Title DEPUTY COUNTY SURVEYOR	STATE
County Surveyor's Comment In addition to the info	rmation shown hereon accurrenal survey
information was collected to verify the right-of	
dedicated on the plat entitled POND EADS A PAUS APRILLED in Book H at Page 50 P.C.R.	

NOTE: THE BEARING AND DISTANCES SHOWN ARE RECORD PER "H"/MAPS/50 P.C.R. NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.

SILVER FIR DRIVE V9004_

SCALE N 1"=30"

LOT 26
MARTISWOODS ESTATES
"N"/maps/27

N 87°56'27" E 100.00'

BOOK 9 CORNER RECORDS PAGE 29